This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images please do not report the images to the Image Problem Mailbox.


CONTINUE TOR AND METHOD OF MANUFACTURE By THOMAS L. WELSH *et al.*

Sheet 1 of 7 Sheets File No. FLN.P.US0002 Phillip L. Kenner, Reg. No. 22,353 Express Mail Label No.EL726133388US



CON TOR AND METHOD OF MANUFACTURE By THOMAS L. WELSH *et al.*

Sheet 2 of 7 Sheets File No. FLN.P.US0002 Phillip L. Kenner, Reg. No. 22,353 Express Mail Label No.EL726133388US




TOR AND METHOD OF MANUFACTURE

By THOMAS L. WELSH *et al*.

Chart 3 of 7 Sharts Phillip L. Kenner Reg. No. 22 363

Sheet 3 of 7 Sheets Phillip L. Kenner, Reg. No. 22,353
File No. FLN.P.US0002 Express Mail Label No.EL726133388US








FIG. 9

5/7



Sheet 6 of 7 Sheets File No. FLN.P.US0002 Phillip L. Kenner, Reg. No. 22,353 Express Mail Label No.EL726133388US



203

FIG. =

Sheet 7 of 7 Sheets File No. FLN.P.US0002

By THOMAS L. WELSH *et al*. Sheets Phillip L. Kenner, Reg. No. 22,353 1002 Express Mail Label No.EL726133388US






FIG. 12